## **National Transportation Safety Board** Washington, DC 20594

## **Brief of Accident**

## Adopted 06/18/1990

DEN	189F	A056
-----	------	------

File No. 47	01/05/1989	ASPEN, CO	Aircraft Reg No. I	N945FE	Tim	ne (Local): 07:39 MST
Engine M Aircra Number o Operating Ce Name Type of Flight	ake/Model: CESSNA / 208B ake/Model: P&W / PT6A-114 it Damage: Destroyed of Engines: 1 rtificate(s): On-demand Air Taxi of Carrier: P. M. AIR, INC. Operation: Non-scheduled; Dometed Under: Part 135: Air Taxi & C	estic; Cargo commuter	Crew Pass	Fatal 0 0	Serious 1 0	Minor/None 0 1
Last Depart. Point: DENVER , CO Destination: Same as Accident/Incident Location Airport Proximity: Off Airport/Airstrip		Condition of Light: Dawn Weather Info Src: Weather Observation Facility Basic Weather: Instrument Conditions Lowest Ceiling: 900 Ft. AGL, Obscured Visibility: 3.00 SM Wind Dir/Speed: Calm Temperature (°C): -1 Obstr to Vision: None Precipitation: Snow				
Pilot-in-Command  Certificate(s)/Rating(s)  Commercial; Multi-engi Instrument Ratings  Airplane	Age: 33 ne Land; Single-engine Land		T	Total Las	me (Hours) All Aircraft: 53 st 90 Days: Ur ake/Model: 32 ment Time: 20	nk/Nr 22

PLT SAID HE ENCOUNTERED SEVERE TO EXTREME TURBULENCE UPON REACHING MISSED APCH POINT AND FELT ACFT MIGHT STALL IF HE BEGAN IMMEDIATE RIGHT TURN AS CALLED FOR IN MISSED APCH PROCEDURE. PLT SAID HE MADE LEFT TURN AT 15 DME (MISSED APCH POINT IS AT 11.5 DME) BECAUSE THERE WAS HIGHER TERRAIN TO RIGHT. ACFT COLLIDED WITH TREES ON MOUNTAIN 3 MI EAST OF ARPT. WX ANALYSIS INDICATED POTENTIAL FOR LIGHT TO MODERATE TURBULENCE BUT NOT SEVERE TO EXTREME TURBULENCE. PLTS LANDING AND DEPARTING ARPT PRIOR TO AND AFTER ACCIDENT REPORTED LIGHT TO CHOP. RADAR SHOWED ACFT SPEED AT 183.1 KTS BETWEEN IAF AND FAF. BETWEEN FAF AND MISSED APCH POINT, ACFT SPEED WAS 95.7 KTS. PLT MODERATE REFERRED TO CURRENT COMMERCIAL INSTRUMENT APCH CHART WHILE EXECUTING APCH. ONLY OBSOLETE GOVERNMENT INSTRUMENT APCH BOOK WAS FOUND IN ACFT. RADIOS WERE NOT TUNED TO MISSED APCH NAVAIDS. PLT-RATED PAX SAID PLT PANICKED AFTER ENCOUNTERING TURBULENCE.

## Brief of Accident (Continued)

DEN89FA056

File No. 47 01/05/1989 ASPEN, CO Aircraft Reg No. N945FE Time (Local): 07:39 MST

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: MISSED APPROACH (IFR)

Findings

1. (F) WEATHER CONDITION - TURBULENCE IN CLOUDS

2. (F) WEATHER CONDITION - LOW CEILING

3. (F) WEATHER CONDITION - OBSCURATION

4. (F) WEATHER CONDITION - SNOW

-----

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: MISSED APPROACH (IFR)

Findings

5. (C) IFR PROCEDURE - IMPROPER - PILOT IN COMMAND

6. TERRAIN CONDITION - MOUNTAINOUS/HILLY

7. OBJECT - TREE(S)

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. PILOT'S IMPROPER IFR PROCEDURE. CONTRIBUTING FACTORS INCLUDED MODERATE TURBULENCE, LOW CEILINGS, OBSCURATION AND SNOW.